



EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
GANGTOK

Memo No.-...268/AE/PK9/Edu.

Date-...05/12/2024

BUILDING SAFETY CERTIFICATE

This is to Certify that a physical inspection of **Green Wood Academy, Rungdung, Rhenock East Sikkim**, was conducted on 4th December by the field engineer of Education Department, Pakyong district.

Block A school building – R.C.C comprise of 5 storeyed with G.C.I roofing having 12 rooms for classes, 1 principal room, Staff room, Dispensary room Indore room Computer Lab and MPH.

Block B school building – R.C.C building comprise of 2 storeyed with G.C.I roofing having 4 class rooms.

Block C School building – R.C.C building comprise of 2 storeyd having Science Lab.


Block D school building – Low cost structure comprise of 2 storeyed having Math Laboratory and 2 class rooms.


Block E school building – Low cost structure comprise of 1 storeyed having Library.

The above said R.C.C structures has been constructed as per the standard construction practices.

Till date the school building has no significant damages or visible defects. Hence, it can be considered fairly safe.

This Certificate is valid for a period of one year from the date of issue.


Junior Engineer
Junior Engineer (Pakyong)
Education Department
Govt. of Sikkim


Assistant Engineer
ASSISTANT ENGINEER
Education Department
Govt. of Sikkim
Pakyong, District