



**EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
GANGTOK**

Memo No: - 107/AE/PKG/EDN

Date-11/02/2026

BUILDING SAFETY CERTIFICATE

This is to Certify that a physical inspection of Green Wood Academy, Rungdung, Rhenock East Sikkim, was conducted on 10th February 2026 by the field engineer of Education Department, Pakyong District.

1. **Block A** - Five storeyed R.C.C structure with G.C.I roofing having 12 rooms for classes, Principal room, Staff room, Infirmary room, Indoor room, Computer lab and Multi-Purpose Hall.
2. **Block B** - Two storeyed R.C.C structure with G.C.I roofing having 4 rooms.
3. **Block C** - Two storeyed R.C.C structure having Science Lab.
4. **Block D** - Two storeyed Low-cost structure having Math Lab and 2 rooms for classes.
5. **Block E** - One storeyed Low-cost structure having Library room.

The visual inspection revealed that the columns, beam and slabs have no cracks or shear stress of any kind, the partition were also found to be free from cracks. Till date the school Building have no significant damages and defects.

Hence, the structures can be certified to be fairly safe.

Junior Engineer (F I)
Junior Engineer
Education Department
Pakyong District

Chhetri
PRINCIPAL
GREENWOOD ACADEMY
RUNG DUNG, RHENOCK
EAST SIKKIM

Subash Poudel
Assistant Engineer
Education Department
Pakyong District

Assistant Engineer (Pakyong)
Education Department
Government of Sikkim

Shinde
MANAGER
GREENWOOD ACADEMY